HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS


HABS No. CA-2614-OO

Oakland Naval Supply Center, Lodge/Cafeteria (Building Number 521) East of 5th Street, between D and E Streets Oakland Alameda County California

David DeVries, Photographer August, 1995 - November, 1995

August, 1993 - November, 1993	
CA-2614-OO-1	SOUTH AND EAST SIDES, FROM E STREET APPROXIMATELY HALFWAY BETWEEN 5TH AND 6TH STREETS, LOOKING NORTHWEST, WITH BUILDING 421 AT FAR LEFT.
CA-2614-OO-2	SOUTH SIDE, CENTER, FROM APPROXIMATELY 40 FEET SOUTH OF BUILDING, LOOKING NORTH.
CA-2614-OO-3	NORTH AND WEST SIDES, FROM SOUTHEAST CORNER OF BUILDING 413, LOOKING SOUTHEAST.
CA-2614-OO-4	COURTYARD/LIGHTWELL ON NORTH SIDE OF BUILDING BETWEEN EAST AND CENTRAL WINGS, FROM APPROXIMATELY 25 FEET WEST OF NORTHEAST CORNER, LOOKING SOUTH.
CA-2614-OO-5	INTERIOR, SECOND FLOOR, ENLISTED MEN'S COMMON AREA ("GOLD ROOM"; SEE FIGURE 86), FROM CENTER OF SOUTH WALL OF ROOM, LOOKING NORTH.

- CA-2614-OO-6 INTERIOR, FIRST FLOOR, MAIN DINING AREA IN CENTRAL WING OF BUILDING NORTH OF MAIN EAST-WEST CORRIDOR, FROM SOUTH WALL, LOOKING NORTH.
- CA-2614-00-7 INTERIOR, KITCHEN/GALLEY, FROM NEAR SOUTHEAST CORNER OF ROOM, LOOKING WEST, WITH PASSAGES TO REFRIGERATION AND FOOD PREPARATION ROOMS AT CENTER.
- CA-2614-OO-8 INTERIOR, SECOND FLOOR, TYPICAL LODGE ROOM (ROOM 28), FROM NORTHWEST CORNER OF ROOM, LOOKING SOUTHEAST, WITH SHOWER STALL IN BATHROOM THROUGH DOOR AT CENTER.



CA-2614-OO-9 INTERIOR, SECOND FLOOR, NORTH-SOUTH CORRIDOR IN WEST WING, FROM ITS INTERSECTION WITH MAIN EAST-WEST CORRIDOR AND NEAR STAIRWELL, LOOKING NORTH.

CA-2614-OO-10 INTERIOR, FIRST FLOOR, MAIN EAST-WEST CORRIDOR, FROM NORTHEAST CORNER OF CENTRAL ENTRY LOBBY ON SOUTH SIDE OF BUILDING, LOOKING EAST, WITH STAIRWAY TO SECOND FLOOR ON LEFT.